

Appendix E – Response from MIRA

From: Sales Front Office <SalesFrontOffice@horiba-mira.com>

Sent: 12 June 2020 15:11

To: Cook, Daniel <Daniel.Cook2@cardiff.gov.uk>

Subject: RE: Partition Screen Testing Query [Public]

Dear Daniel,

Please accept our apologies for the delay in coming back you.

We are now in a position to assess a partition installation on vehicles and provide an installation assessment report to TfL.

However, before we proceed we will need you to provide the following information in advance for preliminary review:

- 1) Evidence that the *screen material* meets the required standard (UN ECE Regulation 43.00) as applicable for either a rigid or flexible plastic glazing partition. You may need to contact the company who supplied your screen to obtain this.
- 2) Are curtain airbags fitted to your vehicle? if so, you must provide details of the curtain airbag deployment pattern, and its expected interaction with the partition. The screen must not impact on airbag deployment or performance. You may need to contact the vehicle manufacturer or the company who supplied your screen to obtain this.
- 3) Vehicle details: Make, model, version and registration number

If you are able to supply the information described above we can proceed to issuing a formal quotation and booking an inspection.

The price for this installation assessment service is £2,150. This is made up of two essential parts:

- £900 for a desktop review of partition screen material specification (compliance to R43 or equivalent)
- £1,250 for a vehicle / screen installation assessment (for a screen that is made of a material that is already “approved” by TFL under item 1)

Please note that HORIBA MIRA is unable to provide partition screens, install them in vehicles or recommend any services to do this work. Please refer enquiries of this nature to TfL.

HORIBA MIRA can only offer an installation inspection service and report on a vehicle where a compliant screen has been installed.

Kind regards

